

BED BASE



A

screw ASM Ø5 x 50 4.8 ZN



12x

B

washer ASM Ø5.0/16 x 1.0 ZN




2x

C

screw TRX Ø4.0 x 16 ZN




2x

E


10x

D

hex key - 3MM ZN




1x

F


1x

G


16x

**H**


12x

**I**


5x

**J**


2x

**K**


3x




1




2



3




3



4


4

5x





5


5x




6



7






8






6


9



10



11



i

